



LED PANNULYKT COB-XPE - 350 RE MANUAL

Vörunummar: 65096

General Safety Instructions:

1. Never look directly into the LED light Source.
2. Must not be immersed in water or other liquids.
3. Must not be operated with wet hands
4. Must never be covered.
5. Must never be operated with an open housing, missing or damaged wiring compartment, or missing or damaged lens.
6. Must never be sprayed or cleaned using a steam pressure cleaner since this can damage the insulation and seals.
7. Must never be repaired by the user, repairs must only be carried out by the manufacturer or an authorized service representative.

Features:

Motion activated sensor (Hand Wave)
Adjustable headband to fit any head size
Type-C USB Charging 5V-1A
IPX4



Technical Data:

LED: 3W COB
Brightness: COB: 350 / 150 lumens Torch: 150 / 60 lumens
Battery: Li-ion 3.7V 1200mAh
Working Time: COB: 2.5 / 5 hrs Torch: 4 / 8 hrs Flash light: 8 hrs
Charging Time: 2.5 hrs

Commissioning:

The light has five switching stage. Short press once on the On/Off switch to go to the next setting, the following setting are possible: COB Full power- COB Half power- Torch Full power - Torch Half power - OFF. Long press on the On/Off button will activate the flash light.

Press the sensor switch to activate the motion sensor, hands wave to turn on or off the light.

Note:

All light are partially charged when delivered.
Charge the product before use fully.
Please do not use the light when charging.
Please do not leave the lamp be in charging over 24 hours.
Please do not disassemble the lamp.
Please recharge the lamp every six months when in stock.

Cleaning:

Allow the light to cool down sufficiently!
Clean with a dry or slightly moist, clean, lint-free cloth and a mild detergent if required.
Do not use cleaners that contain abrasives or solvents.